

Montageanleitung


Mülleimerabdeckungen
Dustbin shelters




Videoanleitung / Instruction movie:
https://youtu.be/lWxjQobKmfc




M8*16 .....




M8*70 .....




D8*75 .....




imbus M8.....




4,8*19 .....



6,3*25 .....



4*8 .....



3,9*16 .....




M8 .....




M8 .....




EPDM 14.....




P8*22 .....




4,2*13 .....



35×40×40 .....




60 × 60 .....



60 × 40 .....


O

Puffer
rubbing strake



T18

Dachblech
roof sheet



BM

Abdeckblende
masking blende



BDL BDF BDP

Dachblende
roof blende

KDT KDL KDF

Dachwinkel
roof bracket

BN

Eckenabdeckung
corner bracket




Z


Dachträger (Z-Profile)
roof beam (Z-plate)


Die Montage des Produkts sollte von einem Montageteam durchgeführt werden, das die Empfehlung des Herstellers besitzt. Eine Montage durch unbefugte Personen erfolgt auf eigene Verantwortung des Kunden. Vor Beginn der Montage sollte überprüft werden, ob der Untergrund ordnungsgemäß vorbereitet wurde. Der Hersteller empfiehlt, das Fundament bis zur Frosttiefe des jeweiligen Gebiets zu verlegen.


The installation of the product should be carried out by an installation team that has the manufacturer's recommendation. Installation by unauthorized persons is performed at the customer's own risk. Before starting the installation, it is necessary to check whether the substrate has been properly prepared. The manufacturer recommends placing the foundation at the frost depth for the given region.

















Die Reihenfolge der Wandmontage gemäß dem vom Hersteller beigefügten Diagramm.
The order of assembling walls according to the schema provided by the manufacturer.





Vorläufiges manuelles Anziehen
(Ohne Verwendung eines Schraubenziehers)


initial manual tightening
(don't use a drill-driver)














Z
Z



M8*16
M8*16



13



4,2*13



6,3*25


10













8


10






4,8*19
EPDM 14



8



KDL
KDF
KDP



20 mm
4*8



4,2
metall



BDL
BDF
BDF
BDP



4*8
3,9*16




















4,2
metall






M8*16



4,2*13
imbus
M8*2
podkł. M8
5



4,2*13
imbu
s
M8*2
podkł. M8
5


10
6
13




4,8*19


2 cm


10
8

Notizen / Notes

GMS Corporation sp. z o.o. ul. Krynicka 55, 33-335 Nawojowa
e-mail biuro@gms-system.com **www** gms-system.com
tel./fax [+48] 184457083 184457093 184457151 184457522

Vertriebsstempel
Distributor stamp